

Delphi Automotive Systems - Diagnostic Trouble Codes List
 AME 300cc Multi Fuel® PROMOT3 Application - MT05

| System or Component | DTC Number | DTC Description |
|---|------------|---|
| Manifold Absolute Pressure Sensor (MAP) | P0107 | MAP Circuit Low Voltage or Open |
| | P0108 | MAP Circuit High Voltage |
| Intake Air Temperature Sensor (IAT) | P0112 | IAT Circuit Low Voltage |
| | P0113 | IAT Circuit High Voltage or Open |
| Coolant/Oil Sensor | P0117 | Coolant/Oil Temperature Sensor Circuit Low Voltage |
| | P0118 | Coolant/Oil Temperature Sensor Circuit High Voltage or Open |
| Throttle Position Sensor (TPS) | P0122 | TPS Circuit Low Voltage or Open |
| | P0123 | TPS Circuit High Voltage |
| Oxygen Sensor | P0131 | O2S 1 Circuit Low Voltage |
| | P0132 | O2S 1 Circuit High Voltage |
| Oxygen Sensor Heater | P0032 | O2S Heater Circuit High Voltage |
| | P0031 | O2S Heater Circuit Low Voltage |
| Fuel Injector | P0201 | Injector 1 Circuit Malfunction |
| | P0202 | Injector 2 Circuit Malfunction |
| Fuel Pump Relay (FPR) | P0230 | FPR Coil Circuit Low Voltage or Open |
| | P0232 | FPR Coil Circuit High Voltage |
| Crankshaft Position Sensor (CKP) | P0336 | CKP Sensor Noisy Signal |
| | P0337 | CKP Sensor No Signal |
| Ignition Coil | P0351 | Cylinder 1 Ignition Coil Malfunction |
| | P0352 | Cylinder 2 Ignition Coil Malfunction |
| Idle Control System | P0505 | Idle Speed Control Error |
| System Voltage | P0562 | System Voltage Low |
| | P0563 | System Voltage High |
| MIL | P0650 | MIL Circuit Malfunction |
| Tachometer | P1693 | Tachometer Circuit Low Voltage |
| | P1694 | Tachometer Circuit High Voltage |
| Oxygen Sensor 2 | P0137 | O2S 2 Circuit Low Voltage |
| | P0138 | O2S 2 Circuit High Voltage |
| Oxygen Sensor Heater 2 or AC clutch | P0038 | O2S Heater 2 Circuit High Voltage |
| | P0037 | O2S Heater 2 Circuit Low Voltage |
| Vehicle Speed Sensor | P0500 | VSS No Signal |
| Park Neutral Switch Diag | P0850 | Park Neutral Switch Error |
| CCP | P0445 | CCP short to high |
| | P0444 | CCP short to low/open |
| BLM MaxAdapt | P0171 | BLM Max Adapt(Kohler Special) |
| BLM MinAdapt | P0172 | BLM Min Adapt(Kohler Special) |
| PE system Lean | P0174 | PE syst Lean(Kohler Special) |
| ECU diagnostic | P0601 | Calibration and software CheckSum fail |